

JAPANESE INDUSTRIAL STANDARD

JIS Z 3060 : 2002

Method for ultrasonic examination for welds of ferritic steel

September 2003

ERRATA

Page 4

7.2.2

Fig.1 RB-41,

No.2 Thickness of over 20 mm up to and incl. 40 mm

Error: $T/2 - 5$

Correct: $T/2$

Remarks: This erratum is for correcting the first edition of this Standard.

Japanese Standards Association

11/20/2014 20:21:51 MDT